RISK ASSESSMENT JS Haulage



Risk Assessment

JS Haulage Ltd Wyebridge House, Cores End Road, Bourne End, Buckinghamshire SL8 5HH

RISK ASSESSMENT JS Haulage

A generic risk assessment for loading and unloading using a Lorry Mounted Crane (LLC) is set out below.

To be read in conjunction with our generic method statement

	avoid or minimise risk	Residual risk
High	Public excluded from site and to establish effective exclusion zone in conjunction with site contact	
High	All operators to wear Hi Viz	Low
High	Ensure lift team are fully briefed on requirement to keep clear of load during lift	Low
High	Ensure continual stabilisers are stowed securely as per LLC Operator Manual	Low
High	Operator to follow safe working methods for use of remote controls in accordance with the Operators Manual Ensure LLC remote control is isolated when not in use Never walk and use LLC	Low
	High High High	High Public excluded from site and to establish effective exclusion zone in conjunction with site contact High All operators to wear Hi Viz Ensure lift team are fully briefed on requirement to keep clear of load during lift High Ensure continual stabilisers are stowed securely as per LLC Operator Manual High Operator to follow safe working methods for use of remote controls in accordance with the Operators Manual Ensure LLC remote control is isolated when not in use

JS Haulage Ltd Wyebridge House, Cores End Road, Bourne End, Buckinghamshire SL8 5HH

RISK ASSESSMENT JS Haulage

Identification of	Residual risk	Control measure to	Residual risk
hazard		avoid or minimise risk	
Lorry loader		Hox	
stability Ground unable to support	Medium	Establish presence of	Low
lorry load	riodidiii	voids or underground services with site	Low
		Assess ground and required size of stabilizer mats	
		Crane supervisor to check matt supplied match those specified in method statement	
Lorry loader overloaded	High	Ensure accurate weight of load is known LLC operator to have valid ALLMI/CPCS card	Low
Lorry loader failure		Ensure LLC has current report of thorough examinations	
Lorry loader becomes unstable	High	winds speeds to be checked before commencement of lift (using the Beaufort scale) and to be aborted if operator manual (also take into consideration the sail effect using the	Low
Working at height		sail effect calculations) Ladder for access/egress	Low
Person falling from height when attaching or removing slings	High	Full fall arrest system to be used when working at height	Low
Environmental Conditions High wind causes load to collide with fixed objects	High	Winds speeds to be checked before commencement of lift (using the Beaufort scale) and to be aborted if operator manual (also take into consideration the sail effect using the sail effect calculations)	Low
Lone Working Operator could become injured	Medium	Where possible avoid long working Ensure operator had up to date contact information for manager Ensure operator follows all safe operating procedures	Low

JS Haulage Ltd Wyebridge House, Cores End Road, Bourne End, Buckinghamshire SL8 5HH

RISK ASSESSMENT JS Haulage

	30 1 10		Γ.
Movement of load	Medium	Tag line attched to load	Low
 Load collides 		control	
with structure			
 Load collides 	High	Establish effective	
with other		exclusion zone in	Low
cranes,		conjunction with site	
•		contact	
excavators etc .	l lieta	Contact	
 Load/lorry load 	High		
boom come		Establish presence of	
within arcing		overhead powerline	Low
distance line			
Persons hand	Medium	If present arrange	
crushed/trapped		isolation or position lorry	
by load		loader 10m = the full	
by toau		length of the boom + any	Low
		protruding load,	2000
		measured along the	
		ground at a position	
		estimated by eye to be	
		directly under the	
		outermost conductor	
		Tag line to be used	
		Gloves to be worn	
		All slinging to be	
		completed by	
		Slinger/Signaller with valid	
		ALLMI/CPCS card	
Suspended load			
 Load may fall 	High	Ensure LLC has current	
onto person		report of thorough	Low
		examination and per-use	
		check carried out	
Loose part on		Ensure lifting accessories	
20000 pa. t o	High	with adequate capacity	
load may fall	1 11811		
		are selected and have	
		current report of thorough	
		examination and per-use	
		check carried out	Low
		Inspect load for loose	
		objects prior to lift and	
		secure/remove loose	
		items	
		пень	
		All life:	1
		All lifting team to wear	Low
		hard hats	

JS Haulage Ltd Wyebridge House, Cores End Road, Bourne End, Buckinghamshire SL8 5HH